

CONSOLIDATED AIRCRAFT CORPORATION
SAN DIEGO, CALIFORNIA

PAGE

MODEL

AIRPLANE





REPORT NO

MARKING & STENCILING
ALL INSIGNIA & MARKING TO
CONFORM WITH SPEC. SR-2A

2825513
Sheet #11 of 20
PBY-5A

EXCEPT AS NOTED OTHERWISE ON 2825502

ALL LETTERS TO BE 1/2" HIGH & PAINTED BLACK EXCEPT AS NOTED

TITLE	INSTRUCTIONS BETWEEN BLKHD. #4 & #5	MARKING
DUMP VALVE HANDLE	ON SUPERSTRUCTURE SKIN ABOVE BOTH DUMP VALVE HANDLE KNOBS	FUEL DUMP VALVE
LOCK FOR MAIN WHEELS	ON PORT & STARBOARD SIDE, ON WEB, STENCIL IN 1/2" RED LETTERS	DOWN LOCK 
	ON PORT & STARBOARD SIDE, ON WEB, STENCIL IN 1/2" RED LETTERS	UP LOCK 
EMERGENCY RELEASE FOR MAIN WHEELS	ON PORT & STARBOARD SIDE ON WEB, STENCIL IN 1/2" RED LETTERS	EMERGENCY RELEASE 
EMERGENCY LOCKING MECHANISM	10" ABOVE EMERGENCY DOOR ON PORT AND STARBOARD SIDE STENCIL IN 1/2" RED LETTERS	EMERGENCY LOCKING MECHANISM
EMERGENCY DOOR	ON DOOR, STENCIL IN 1/2" RED LETTERS	EMERGENCY DOOR
PROPANE STOVE STOWAGE	STENCIL ON ANGLE OF EACH STOWAGE BRACKET L & R	PROPANE STOVE
EMERGENCY RELEASE DOWN LATCHING ROD	TO CONFORM WITH 28L5088	
LUBRICATION OF LANDING GEAR	ON PORT AND STARBOARD SIDE ON REINFORCING ANGLE AFT SIDE FRAME #4.50 WITH ARROW POINTING TO ZERK FITTINGS - STENCIL	LUBRICATE GEAR 
SLING STOWAGE	STENCIL ON FORWARD SIDE OF WEB BULKHEAD #5 THREE PLACES	SLING
ENGINE CRANK STOWAGE	PORT SIDE ON SKIN BETWEEN FRAMES 3.50 & 3.75 IN VICINITY OF STRAP - STENCIL	ENGINE CRANK
CRANK STOWAGE	STARBOARD SIDE AFT BULKHEAD #4 IN VICINITY OF STRAP - STENCIL	RETRACTABLE FLOAT AND ANCHOR CRANK

BY

CHECKED

APPROVED